
# ESSEX POLICE, FIRE AND CRIME COMMISSIONER FIRE & RESCUE AUTHORITY





Meeting	Performance and Resources Board	Agenda Item No.	8	
Meeting Date	28 June 2021			
Report Authors:	WM Jon Webster			
Presented By	ACFO Moira Bruin, Director of Operations			
Subject	Fire Protection Board Building Risk Review Update			
Type of Report:	Information			

### RECOMMENDATIONS

None. This is an update report and should be treated as containing potentially sensitive information.

### OVERVIEW

This report provides an update on progress against the National Fire Chiefs Council (NFCC) Building Risk Review: August 2020 to December 2021.

# BACKGROUND

Following the outcomes of the Grenfell Tower Inquiry, the NFCC Instigated a Building Risk Review. The NFCC Identified and communicated to Essex 182 buildings which need to be visited and assessed. Essex were asked to report back on a confirmed inspection regime for the identified buildings from August 2020 until December 2021 (attached).

This report details the 15 building inspections carried out from 1<sup>st</sup> May to 31<sup>st</sup> May 2021. Returns were submitted to the NFCC by 10<sup>th</sup> June 2021. This return has met with the proposed trajectory of 15 audits for May 2021.

This Building Risk Review regime is being managed by the Head of Protection and the Area Manager Protection and Prevention. The Head of Protection prepares a monthly return which is to be submitted on the 10th of each month to report on progress.

In the table below, the "External Wall System/Audit Details" bullet point answers relate to the following questions:

- From information available at the time, can the make-up of the External Wall System (EWS) be identified?
- If so, what is the type of cladding?
- If so, what is the type of insulation?
- How was the type of cladding system confirmed by the Responsible Person (RP)?
- What letter was issued FSO 02 or FSO 03?

Premises name and identifying number	Location /address	External Wall System/Audit Detalls	Issues/Further Action	RAG	Building Type
		Yes     ACM Rainscreen     None     EWS Engineers Report     FSO 03		R	Residential 07 Storey
		Yes     ACM Rainscreen     None     EWS Engineers     Report     PSO 03		R	Residential 07 Storey
		Yes     ACM Rainscreen     None     EWS Engineers     Report     PSO 03		R	Residential 07 Storey
		No Partial fibre cement plank ("Hardie Plank") & spandrel panel Unknown No further information from		А	Residential 06 Storey
		No Partial fibre cement plank ("Hardie Plank") & spandrel panel Unknown No further information from RP		А	Residential 04 Storey
		No Partial fibre cement plank ("Hardie Plank") & spandrel panel Unknown No further information from RP		А	Residential 05 Storey
		No     Partial fibre cement plank		A	Residential 05 Storey

		_	•
("Hardie Plank") &			
spandrel panel  Unknown			
No further			
information from			
RP			
• No	-		Residential
<ul> <li>Partial fibre</li> </ul>			05 Storey
cement plank			_
("Hardie Plank") &		A	
spandrel panel  Unknown			
No further			
information from			
RP			
• No			Residential
<ul> <li>Partial fibre</li> </ul>			05 Storey
cement plank			
("Hardie Plank") & spandrel panel		А	
Spandrel panel     Unknown		A.	
No further			
information from			
RP			
• No			Residential
Partial fibre			06 Storey
cement plank ("Hardie Plank") &			
spandrel panel		A	
<ul> <li>Unknown</li> </ul>			
No further			
information from			
RP • Yes	-		Residential
Yes     None			08 Storey
None		G	
None Applicable			
<ul> <li>FSO 02</li> </ul>			
Yes			Residential
None			08 Storey
None     None Applicable		G	
FSO 02			
• Yes			Residential
None			08 Storey
• None		G	
<ul> <li>None Applicable</li> </ul>			
• FSO 02			
Yes     Rain screening			Residential 06 Storey
Kain screening     fibre cement plank			ou storey
Glass Fibre		G	
<ul> <li>FRC Facade Report</li> </ul>			
& EWS by Tri Fire			
<ul> <li>FSO 03</li> </ul>			
• Yes			Residential
<ul> <li>Rain screening fibre cement plank</li> </ul>		G	06 Storey
Glass Fibre			
- vilass riúfe			

	<ul> <li>FRC Facade Report</li> </ul>		
	& EWS by Tri Fire		
	<ul> <li>FSO 03</li> </ul>		

#### ISSUES

From the initial inspections conducted, on most we have been unable to ascertain the exact construction of the external wall system as the Responsible Person was unaware at the time of the visit. The NFCC reporting spreadsheet allow a response of YES/NO/DON'T KNOW in response to the question "Can the make up of the External Wall System (EWS) be identified?".

in order to gather accurate data we have produced a letter which is being sent out when organising the inspection to advise those responsible of what questions we will be asking. If the information is not available at the time of the inspection, further letters are being sent requesting that information be provided. All data retrieved is held on a master spreadsheet which is also shared with the Operations Department.

Premises where we cannot identify the material but it is clearly not Aluminium Composite Material (ACM) or High Pressure Laminate (HPL) have been marked as an amber risk on the table. If ACM or HPL is present and there is no mitigation in place, it will be marked as red in the RAG column.

### PROGRESSION

Essex County Fire and Rescue Service are not on track with the trajectory agreed with the NFCC. Submissions will continue to be made to the NFCC on the 10<sup>th</sup> of each Month until December 2021 and update reports will continue to be submitted to SLT and P&R board for monitoring and awareness.

The NFCC originally identified 182 premises for ECFRS to investigate. ECFRS records initially identified 15 premises in addition to the 182 that should be examined, bringing the initial total to 197 premises.

As the Building Risk Review is being undertaken, additional buildings are being identified that will require an audit. It has been agreed that as a general rule, newly identified premises will be audited once the initial 197 have been audited. There are currently 62 premises on this list.

- Therefore, as of end of May 2021, the total number of buildings to be audited as part of the Building Risk Review stands at 259 (245 last month).
- As of the end of May 2021, 119 audits have been completed.

# REMEDIATION (Premises to date)

PREMISES	ECFRS UPRN	BUILDING TYPE	NOTES	FSO27 ISSUED	PSO 57 ISSUED	NOTES
	!					





# FINANCIAL IMPLICATIONS

'Surge funding' has been received by ECFRS to enable additional targeted assessment to be carried out. This is covered in a separate paper.

# EQUALITY AND DIVERSITY IMPLICATIONS

This decision is not anticipated to have an impact on any of the following protected groups as defined within the Equality Act 2010:

Race	N	Religion or belief	N
Sex	N	Gender reassignment	N
Age	N	Pregnancy & maternity	N
Disability	N	Marriage and Civil Partnership	N
Sexual orientation	N		

# WORKFORCE ENGAGEMENT

Workforce and rep bodies have been engaged

## LEGAL IMPLICATIONS

The Fire and Rescue National Framework for England lays down a priority for fire and rescue authorities to make appropriate provision for fire protection and prevention activities.

### HEALTH AND SAFETY IMPLICATIONS

Individual assessments of each of the 182 buildings identified by the NFCC will enable any issues to be identified and addressed which will improve any potential risks to the Health and Safety of occupants and crews responding to incidents.